Fig.1




Fig.2A





Fig.2B




greek first first first from our -d -d -d -d -d first mak from first from

30 476

The left her Ch her with all a de the wall has the first with her first had been send that had





OBLON ET AL (703) 413-3000 DOCKET # 198778US2DIV SHEET <u>3</u> OF <u>17</u>





Fig.5










Fig.7









Fig.10



OBLON ET AL (703) 413-3000 DOCKET # 198778US2DIV SHEET <u>8</u> OF <u>17</u>

Fig.11A




Fig.11B




Fig.12





Fig.13



Hall the Brown week from the He

OBLON ET AL (703) 413-3000 DOCKET # 198778US2DIV SHEET <u>10</u> OF <u>17</u>






Fig.15




Fig.16




Fig.17





Fig.18







Fig.20






Fig.21A





Fig.21B






Fig.22




Fig.23A






Fig.23B











Fig.24B



OBLON ET AL (703) 413-3000 DOCKET # 198778US2DIV SHEET <u>16</u> OF <u>17</u>







OBLON ET AL (703) 413-3000 DOCKET # 198778US2DIV SHEET <u>17</u> OF<u>17</u>

Taping Deburring Test Molding Cutting/ bending Marking W/B connecting material Conductive Plating D/B Lead frame — (Copper alloy) Dicing

PRIOR ART FIG. 27